

## **Linear Actuators**

smoovy® Technology

## 2,8 N

For combination with Brushless DC-Motors

## Series 03A S3

	03A S3
Housing material	plastic
Geartrain material	steel
Screw material	steel
Nut material	bronze
Recommended max. input speed for:	
– continuous operation	15 000 rpm
Max. linear travel	7 mm
Bearings on output shaft	bronze
Shaft play (2 mm from mounting face):	
– radial	≤ 0,07 mm
– axial	≤ 0,15 mm
Operating temperature range	- 20 + 60 °C

Specifications				
Number of gear stages		2	3	
Push force, continuous	N	0,47	2,8	
Push force, intermittent	N	0,7	4,2	
Weight without motor, ca.	g	0,36	0,34	
Max. speed	mm/min	120	24	
Direction of rotation, drive to outp	ut	=	=	
Reduction ratio		25:1	125:1	
(exact)				
<b>L2</b> [mm] = length without motor		6,0	6,0	
L1 [mm] = length with motor 0308	BAB	12,6	12,6	
-				

Note: These gearheads are available only with motors mounted.

Capability of pushing/pulling the nut requires a bearing at the end of the shaft.

