

## Planetary Gearheads 32/3

Gearhead Series	Reduction ratio	Number of gear stages	3D - File Name
32/3 (with ball bearings on output shaft)	3,71:1	1	32_3 1stage.stp
	14,1:1	2	32_3 2stages.stp
	43:1	3	32_3 3stages.stp
	66:1	3	32_3 3stages.stp
	134:1	4	32_3 4stages.stp
	159:1	4	32_3 4stages.stp
	246:1	4	32_3 4stages.stp
	415:1	5	32_3 5stages.stp
	592:1	5	32_3 5stages.stp
	989:1	5	32_3 5stages.stp
	1526:1	5	32_3 5stages.stp

## Conditions of Use

The FAULHABER CAD 3D-Drawings are a free service of FAULHABER MINIMOTOR SA, 6980 Croglio, Switzerland. They may only be used and distributed in a complete and unaltered form. All copy rights reserved.

Please Note: All dimensions are displayed using the metric system (millimeters). Your CAD system maybe preset to another system of measurements or dimenstions. Preset millimeter in the CAD application before importing the file!

These models are intended as a conceptual aid only. All dimensions are subject to change without notice. The most up-to-date drawings can be downloaded from the Internet at: [www.faulhaber.com](http://www.faulhaber.com)

Though we endeavor to maintain the accuracy of the models provided we can provide no guarantee of their accuracy. Use of the models is at your own risk.

With the use of the data you agree with the aforementioned conditions.